SECRET

GROUP 1 So Excluded from automatic downgrading and declassification

BETWEEN FRAMES 299/300, 899/900, AND 1199/1200.

(2) 9L SIDE: A MANUFACTURING SPLICE IS PRESENT IN FRAME 1975. THERE IS A HEAT SPLICE IN FRAME 953 AND BETWEEN FRAMES 299/300, 599/600, 1199/1200, 1499/1500.

E. AUXILIARY DATA: THE COUNTER IN THE DATA CHAMBER SKIPPED A NUMBER ON FRAME 21. THE COUNTER AND THE TITLING AGREE UP TO AND INCLUDING FRAME 20. COUNTER NUMBER 22 CORRESPONDS TO TITLED FRAME 21 AND THIS BIAS CONTINUES TO THE END OF THE MISSION. ALL OTHER DATA RECORDING EQUIPMENT FUNCTIONED PROPERLY.

F. OTHER: ALL ODD NUMBERED FRAMES OF THE RIGHT SIDE ARE TITLED 31 JULY 1968 INSTEAD OF 13 JULY 1968. THE LAST TITLED FRAME OF BOTH SIDES IS 2044.

3. POSITIVES

A. THE PRINTING AND PROCESSING WERE GOOD WITH THE EXCEPTION OF THE FIRST ONE-THIRD OF THE MISSION. THE PHOTOINTERPRETERS CONSIDERED THE DENSITY OF THIS PORTION TO BE HEAVY FOR SUITABLE INTERPRETATION.

B. PART ONE OF THE LEFT SIDE WAS NOT RECEIVED AT THIS FACILITY; INSTEAD, TWO COPIES OF PART FOUR WERE RECEIVED. GP-1

SECRET

END OF MESSAGE